



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/EXV/QAR18.0001/05	Page 1 of 1															
QAR Free Ref. No.:	R6512/A/1	Status: Issued															
Details of change:	Recertification audit conducted	Date of issue: 2026-07-29															
Location(s) audited:	Ionix Advanced Technologies Limited Lynthorne House Intercity Way Leeds LS13 4LQ United Kingdom	Valid until: 2029-07-21 Audit date: 2026-07-23															
Issuing ExCB:	EXV - ExVeritas Limited																
Manufacturer:	Ionix Advanced Technologies Limited Lynthorne House Intercity Way Leeds LS13 4LQ																
Location of Manufacturer:	United Kingdom																
Product information:	HotSense™ High Temperature Ultrasonic Transducer TRND Ultrasonic inspection monitoring system																
Type of protection:	Ex “i”																
Related QARs:	GB/EXV/QAR18.0001/00 GB/EXV/QAR18.0001/01 GB/EXV/QAR18.0001/02 GB/EXV/QAR18.0001/03 GB/EXV/QAR18.0001/04																
Related Certificates (manual insertion)::																	
Related Certificates (automatic linking)::																	
Related Certificates for previous versions:	<table><tr><td>IECEX EXV 18.0009X issue: 0</td><td>IECEX EXV 18.0009X issue: 1</td><td>IECEX EXV 18.0009X issue: 2</td></tr><tr><td>IECEX EXV 18.0009X issue: 3</td><td>IECEX EXV 18.0009X issue: 4</td><td>IECEX EXV 18.0009X issue: 5</td></tr><tr><td>IECEX EXV 21.0019X issue: 0</td><td>IECEX EXV 21.0019X issue: 1</td><td>IECEX EXV 21.0019X issue: 2</td></tr><tr><td>IECEX EXV 22.0031X issue: 0</td><td>IECEX EXV 22.0031X issue: 1</td><td>IECEX EXV 22.0031X issue: 2</td></tr><tr><td>IECEX EXV 25.0027X issue: 0</td><td></td><td></td></tr></table>		IECEX EXV 18.0009X issue: 0	IECEX EXV 18.0009X issue: 1	IECEX EXV 18.0009X issue: 2	IECEX EXV 18.0009X issue: 3	IECEX EXV 18.0009X issue: 4	IECEX EXV 18.0009X issue: 5	IECEX EXV 21.0019X issue: 0	IECEX EXV 21.0019X issue: 1	IECEX EXV 21.0019X issue: 2	IECEX EXV 22.0031X issue: 0	IECEX EXV 22.0031X issue: 1	IECEX EXV 22.0031X issue: 2	IECEX EXV 25.0027X issue: 0		
IECEX EXV 18.0009X issue: 0	IECEX EXV 18.0009X issue: 1	IECEX EXV 18.0009X issue: 2															
IECEX EXV 18.0009X issue: 3	IECEX EXV 18.0009X issue: 4	IECEX EXV 18.0009X issue: 5															
IECEX EXV 21.0019X issue: 0	IECEX EXV 21.0019X issue: 1	IECEX EXV 21.0019X issue: 2															
IECEX EXV 22.0031X issue: 0	IECEX EXV 22.0031X issue: 1	IECEX EXV 22.0031X issue: 2															
IECEX EXV 25.0027X issue: 0																	

Comments: